



#### PHASE I ENVIRONMENTAL PROPERTY ASSESSMENT

2325 Wisconsin Street Downers Grove, Illinois

#### Prepared For:

American National Bank & Trust Company of Chicago 120 South LaSalle Street, Mail Code IL 1-1201 Chicago, Illinois 60603

Prepared By:

EPS Environmental Services, Inc.

7237 West Devon Avenue Chicago, Illinois 60631

> Brian I. Thomas Project Manager

i Toject Ivianago

Reviewed By:

Peter N. Partipilo, C.H.M.M. Senior Environmental Specialist

Project Number:

3899-1001

November 1, 2001



### TABLE OF CONTENTS

1.0	Sumr	nary	1
2.0	Introd	duction	
2.0	2.1	Purpose	
	2.2	Scope of Services	
	2.3	Limiting Conditions.	
3.0	Prope	erty Description	3
	3.1	Location and Legal Description	
	3.2	Description of Improvements On-Site	
	3.3	Current and Past Uses of the Property	4
	3.4	Current and Past Uses of Adjoining Sites	
4.0	Reco	rds Review	5
	4.1	Physical Setting Sources	5
	4.2	Federal and State Environmental Record Sources	6
	4.3	Historical Use Information	9
5.0	Interv	riews	10
6.0	Site F	Reconnaissance	10
	6.1	Underground Storage Tanks (USTs)	
	6.2	Aboveground Storage Tanks (ASTs)/Storage Drums/Containers	10
	6.3	Stained Surfaces/Stressed Vegetation	
	6.4	Stormwater Run-off/Standing Water	
	6.5	Waste Disposal Practices	11
	6.6	Polychlorinated Biphenyls (PCBs)	11
	6.7	Air Quality/Emissions	12
	6.8	Readily Visible Suspect Asbestos-Containing Material (ACM)	12
	6.9	Potential Lead-based Paint	13
• •	6.10	Miscellaneous Equipment	13
	6.11	Observations of Surrounding Sites	13
7.0	Warra	anty and Limitations of Liability	14
		FIGURES	
Figure	2 1 - Pro	perty Location Map	
Figure	2 - Pro	perty Sketch	
		lding Sketch	
Ü		APPENDICES	
Apper	ndix A -	Photographic Documentation	
		Environmental Database Information	
		Historical Information	
		Environmental Questionnaire	
		EPS Environmental Qualifications	
		Proposal between Client and EPS Environmental	



#### 2.0 INTRODUCTION

EPS Environmental was retained to conduct the Phase I Assessment of the Property by American National Bank & Trust Company of Chicago (Client).

#### 2.1 Purpose

The purpose of the Phase I Assessment was to identify readily apparent, potential sources of environmental liabilities associated with the Property.

#### 2.2 Scope of Services

The scope of services performed by EPS Environmental was set forth in the Proposal between the Client and EPS Environmental, dated October 18, 2001, a copy of which is attached hereto and made a part hereof, as Appendix E.

#### 2.3 Limiting Conditions

The presence of stockpiled materials, various floor coverings and heavy machinery limited observations of underlying interior surfaces in several isolated areas. The presence of parked automobiles and landscaping limited observations of exterior surfaces. Therefore, EPS Environmental makes no guarantees as to the condition of the underlying surfaces or areas not observed.

Sampling and an all-inclusive survey for the presence of suspect asbestos containing material (ACM) were beyond the scope of services for this Phase I Assessment. A visual inspection for readily observable suspect ACM was conducted; moreover, the removal of physical or visual barriers or inaccessible areas such as pipe chases, interiors of machinery/equipment and "dead spaces," such as fully enclosed masonry vaults, was not conducted as part of this Phase I Assessment.

Access to the rooftop of the structure was not provided. Therefore, EPS Environmental makes no guarantees as to equipment which may be present on the roof. However, EPS Environmental did not observe rooftop equipment of environmental significance as viewed from the ground.

As a Plat of Survey was not provided for the Property, exact Property boundaries could not be determined and the size of the Property and structure has been estimated.

Any other limiting conditions pertaining to this Phase I Assessment are described in associated Sections of this Report.



#### 3.0 PROPERTY DESCRIPTION

#### 3.1 Location and Legal Description

The Property is located on the south side of Wisconsin Street, approximately 1¼ mile east of the East Branch of the DuPage River in the Village of Downers Grove, DuPage County, Illinois. The Property is situated in a mixed industrial and residential setting. (See Figure 1 - Property Location Map, following the text of this Report). The legal description for the Property was not provided.

#### 3.2 Description of Improvements On-Site

#### 3.2.1 Property Size

The Property consists of a rectangular shaped parcel of land encompassing approximately 130,000 square feet.

#### 3.2.2 Structure

The Property is developed with a one-story tall, 43,000 square foot structure. The structure consists of an approximate 17,000 square foot original building and an approximate 26,000 square foot addition.

#### 3.2.2.1 General Construction

The 39-year-old original building and 18-year old addition are similarly constructed of masonry, concrete and steel on slab foundation.

#### 3.2.2.2 Interior Finishes

Typically, the interior of office and common areas of the structure consists of carpeted and/or vinyl tiled floors, gypsum board and/or wood paneled walls and drop paneled and/or plaster ceilings.

The warehouse/production areas consist of concrete floors, masonry walls, and a steel truss ceiling.

#### 3.2.2.3 Heating and Cooling Sources

The original building is heated and cooled by a natural gas-fired, heating, ventilation and air-conditioning (HVAC) unit and a natural gas-fired boiler with associated hot water/steam radiant lines, which is located in the original building.



#### 1.0 SUMMARY

EPS Environmental Services, Inc. (EPS Environmental) has performed a Phase I Environmental Property Assessment (Phase I Assessment) in conformance with the scope and limitations of ASTM Practice E 1527-00 of 2325 Wisconsin Street, Downers Grove, Illinois (Property). Any exceptions to, or deletions from, this practice are described in Section 2.3 of this report (Report). This Phase I Assessment has revealed no evidence of recognized environmental conditions in connection with the Property except for the following:

- The Property may have been negatively impacted by current and/or historical metal plating operations on the Property.
- There is a potential for contaminants to have migrated onto the Property from Underground Storage Tanks (USTs) located on the west adjacent site. The west adjacent site is listed on the United States Environmental Protection Agency (USEPA) Handlers with Corrective Action Activity (CORRACTS), USEPA No Further Remedial Action Planned (NFRAP), RCRIS generator databases and the Office of the State Fire Marshall's (OSFM) registered USTs.
- Readily visible suspect friable and non-friable asbestos-containing material (ACM) was noted in and on the structure.
- The painted surfaces of the structure may contain lead above regulatory limits.
- It is possible the ballasts within the fluorescent light fixtures and fluids within air compressors in the structure contain polychlorinated biphenyls (PCBs).
- It is possible the fluorescent bulbs and thermostats located in the structure contain mercury.
- Air conditioning units, which contain chlorofluorocarbon (CFC) refrigerant, are located on the Property.



The addition is heated and cooled by a natural gas-fired, heating, ventilation and air-conditioning (HVAC) unit.

#### 3.2.3 Remaining Grounds

The remaining grounds consist of an asphalt parking area west and north of the structure and landscaping east and north of the structure.

Refer to Figure 2 - Property Sketch, and Appendix A - Photographic Documentation, following the text of this Report.

#### 3.2.4 Potable Water Source

The DuPage Water Commission supplies drinking water from Lake Michigan to the Property. The water is collected and treated by the Downers Grove Sanitary District, located at 2710 Curtis Street in Downers Grove, Illinois. According to the Water Department, the water is tested periodically for contaminants and is in compliance with all EPA drinking water regulations, unless a local drinking water advisory has been issued.

#### 3.2.5 Wastewater/Stormwater Discharge

Wastewater and stormwater run-off within the Village of Downers Grove are discharged into separate sewer systems. The sanitary effluent is collected and treated by the Downers Grove Sanitary District. The stormwater run-off is collected by on-site sewers and discharged into local waterways. The wastewater from the dip tanks in the hazardous materials room is discharged into a concrete pit lined with fiberglass which is neutralized and discharged into the sewer system.

#### 3.3 Current and Past Uses of the Property

#### 3.3.1 Current Uses

The Property is currently occupied by Tricon Industries. Inc. (Tricon) and used for office and light industrial purposes. Tricon is an insert molder and specialized component manufacturer for worldwide automotive, mobile communications and appliance markets. Tricon's operations utilize, store, and/or handle hazardous substances that include cyanide, acids, caustics, metals and/chlorinated solvents. Operations include stamping, cutting, milling, machining of metal parts, and metal plating as well as plastic injection molding.



#### 3.3.2 Past Uses

\

The Property has been occupied by Tricon since original construction circa 1960. Prior to Tricon, the Property consisted of vacant land.

See Section 4.3 - for information on the historical use review regarding the Property.

#### 3.4 Current and Past Uses of Adjoining Sites

#### 3.4.1 Current Uses

The Property is surrounded as follows:

North Wisconsin Street

MXL (manufacturer of plastic injection moldings) - 2300 Wisconsin Street

East Magnetrol (manufacturer of electronic components) – 5300 Belmont Road

Belmont Road

South Single-family dwellings

West Suburban Self-Storage (storage facility) – 2333 Wisconsin Street

Janes Avenue

#### 3.4.2 Past Uses

The surrounding sites have historically been utilized for industrial and residential purposes since development.

#### 4.0 RECORDS REVIEW

#### 4.1 Physical Setting Sources

The following sources were reviewed to provide information on the topographic and geologic characteristics of the Property and surrounding area. Additionally, a county radon study was reviewed to provide statistics on the Property's potential radon risk.



#### 4.1.1 U.S. Geological Survey 7.5 Minute Series Topographic Map

According to the Wheaton Quadrangle map, the general topography of the area displays an approximate five-foot decrease in elevation within ¼ mile northwest of the Property.

#### 4.1.2 Illinois State Geological Survey Circular #460, "Surficial Geology of the Chicago Region"

The Property is located on the Mackinaw Member of Henry Formation. This Pleistocene Age system consists of sand and gravel, generally well-sorted and evenly bedded; deposits in valleys; mostly glacial outwash in terraces, which are remnants of valley trains, and includes similar deposits in glacial sluiceways.

## 4.1.3 Illinois State Geological Survey Circular #532, "Potential for Contamination of Shallow Aquifers from Land Burial of Municipal Waste"

The Property is located in an area rated as C1. The rating denotes the capacities of earth material to accept, transmit, restrict or remove contaminants from waste effluent. In general, a C1 rating area contains permeable bedrock within 20 to 50 feet of the surface, overlain by till or other fine-grained material.

## 4.1.4 Illinois Department of Nuclear Safety, "Radon In Illinois: A Status Report" Update December 1990

The Property is located in DuPage County in which 17% of homes tested had radon levels greater than 4.0 picocuries per liter (pCi/L). The level of 4.0 pCi/L is the standard set by the EPA. An average level of 4.4 pCi/L was detected among the 166 homes screened. This screening data is included as a guide to background conditions and should not be construed as site-specific data. Radon is of lesser concern for buildings constructed on concrete slab foundations, as is the case of the Property.

#### 4.2 Federal and State Environmental Record Sources

The following federal and state databases were reviewed for recorded environmental concerns on the Property and known sites within the Approximate Minimum Search Distance, as designated in ASTM Standard E 1527-00. Refer to Appendix B - Environmental Database Information, for the listings of sites identified within the study area.

• United States Environmental Protection Agency (USEPA) National Priority List (NPL), January 2001 - 1 mile search distance



- USEPA Comprehensive Environmental Response, Compensation and Liability Information System (CERCLIS), May 2001 ½ mile search distance
- USEPA CERCLIS No Further Remedial Action Planned (NFRAP), May 2001 Property and adjacent sites
- USEPA Resource Conservation and Recovery Act Information System (RCRIS) Treatment, Storage and Disposal (TSD) facilities, August 2001 ½ mile search distance
- USEPA RCRIS Generator and Transporter facilities, August 2001- Property and adjacent sites
- USEPA Handlers with Corrective Action Activity (CORRACTS), April 2000 1 mile search
- USEPA Emergency Response Notification System (ERNS), January 2000- Property only
- IEPA Site Remediation Program (SRP), October 2001 1 mile search distance
- Northeastern Illinois Planning Commission (NIPC) Database, December 1987 ½ mile search distance
- Illinois Environmental Protection Agency's (IEPA) List of Land-Based Disposal Sites (LBDS) solid waste, various dates ½ mile search distance
- IEPA Leaking Underground Storage Tank (LUST) Incident Report, October 2001 ½ mile search distance
- Office of the State Fire Marshal (OSFM) Registered Underground Storage Tanks (USTs), June 2001 - Property and adjacent sites

The Property was identified on the USEPA RCRIS generator database. Additionally, one (1) adjacent registered UST/CORRACTS/NFRAP/RCRIS generator site, two (2) adjacent RCRIS generator sites, three (3) LUST sites and one (1) SRP site were identified within the search distances.

The Property was identified on the RCRA database as a small quantity generator of hazardous waste. Tricon generates hazardous waste in the form of acid liquid, alkaline liquid, chlorinated solvents, copper, nickel, zinc, and cyanide. The hazardous waste is collected in 55-gallon storage drums and transported off-site by Heritage Environmental for final disposal/recycling. Provided the



hazardous waste is and was properly handled, stored, and disposed, the RCRIS database listing as a small quantity generator of hazardous waste should not present a readily apparent environmental concern to the Property.

The west adjacent site, 2333 Wisconsin Street, Suburban Self Storage, appeared on the OSFM database of registered USTs under the facility name Liberty Copper & Wire Co. with one, "exempt from registration" UST and four, "removed" USTs. The "exempt from registration" UST was identified as a 4,000-gallon tank and the "removed" USTs were identified as three 4,000-gallon "hazardous" USTs and one, 5,000-gallon "hazardous" UST. No evidence of equipment likely associated with these USTs were observed on this adjacent site from Property borders and public thoroughfares during EPS Environmental's on-site inspection. This site was also identified on the CORRACTS database. A Freedom of Information Act (FOIA) request has been submitted to the United States Environmental Protection Agency (USEPA) for additional information regarding this listing. However, a response had not been received at the time of this writing. In the event environmentally significant information is received, that would alter the Findings and Conclusions of this Report, it will be promptly forwarded to the Client. The NFRAP designation indicates, to the best of the USEPA's knowledge, assessment at the site has been completed and that the USEPA has determined no further steps will be taken to list this site on the National Priorities List (NPL), unless information indicates this decision was not appropriate or other considerations require a recommendation for listing at a later time. This decision does not necessarily mean there is no hazard associated with a given site; it only means that, based upon available information, the site is not judged to be a potential NPL site. This site was also identified on the RCRA generator database as a generator of hazardous waste. No outside hazardous waste storage areas or signs of deliberate dumping of waste were observed at this site during the EPS Environmental site reconnaissance. Provided the hazardous waste on the adjacent site is properly handled, stored, and disposed, this site's RCRIS database listing as a large quantity generator of hazardous waste should not present a readily apparent environmental concern to the Property.

The east and south adjacent sites were identified on the RCRA generator database as generators of hazardous waste. No outside hazardous waste storage areas or signs of deliberate dumping of waste were observed at the sites during the EPS Environmental site reconnaissance. Provided the hazardous waste on the adjacent sites are properly handled, stored, and disposed, the sites' RCRIS database listings as generators of hazardous waste should not present a readily apparent environmental concern to the Property.

The three (3) recorded LUST sites identified are located over 1/8-mile from the Property. Based on the physical distances from the Property none of the LUST sites identified within the 1/2-mile study radius are expected to present an environmental concern to the Property.



The recorded SRP site identified is located over ¼ mile from the Property. The SRP site was granted a "No Further Remediation" (NFR) status (closed status) by the IEPA. Based on the physical distance from the Property and the closed status, the recorded SRP site identified within the one-mile study radius is not expected to present an environmental concern to the Property.

#### 4.3 Historical Use Information

The following reasonably obtainable sources of information were reviewed or contacted to determine the historical uses of the Property. When feasible, information pertaining to the adjacent sites was reviewed.

4.3.1 1951, 1970, 1980 and 1990 Aerial Photographs (Aerials) - provided by Chicago Aerial Photo Services, Inc., Northern Illinois Planning Commission (NIPC) and reviewed at the University of Illinois at Chicago Library

The 1951 Aerial depicted the Property and adjacent sites as undeveloped land. The 1970 and 1980 Aerials depicted the Property with the original building. The 1990 Aerial depicted the Property and surrounding sites to currently identified. There was no significant disturbance to upper soil layers or evidence of open dumping on the Property or surrounding sites on any Aerials reviewed. See Appendix C - Historical Information for a copy of the Aerials reviewed.

4.3.2 <u>Historical Building Permits, via Freedom of Information Act (FOIA) request and file review at the Village of Downers Grove Community Development Department</u>

A response from the Village of Downers Grove revealed no permits of environmental significance for the Property.

4.3.3 Fire Department Records, via FOLA request to the Village of Downers Grove Fire Department

A FOIA request was submitted to the Village of Downers Grove Fire Department regarding the Property and adjacent sites; however, at the time of this writing a response had not been received. In the event information is received that alters the Findings and Conclusions of this Report, it will be forwarded promptly to the Client.

4.3.4 Zoning, via FOIA request at the Village of Downers Grove Community Development Department

According to a response from the Zoning Department, the Property is zoned M-2, light manufacturing district.



#### 5.0 INTERVIEWS

The following individuals were interviewed for specialized knowledge concerning the Property. The relevant information provided by these individuals has been incorporated in the appropriate Sections of this Report.

Mr. Larry McDaniel -

Tricon Industries, Inc. - Plant Manager — Accompanied, and interviewed by, EPS Environmental personnel during site reconnaissance (630-964-2330). Completed Environmental Questionnaire which is included as Appendix D.

Local Officials

#### 6.0 SITE RECONNAISSANCE

The site reconnaissance was conducted on October 29, 2001 at approximately 10:00 a.m. Mr. Samuel T. Bodine, Senior Project Manager, and Mr. Brian J. Thomas, Project Manager for EPS Environmental (Appendix E). The site reconnaissance was initiated by observing the Property and adjacent sites from public thoroughfares, continued by inspecting the interior of the structure and concluded by walking the Property boundaries. Photographic documentation of significant environmental features has been included as Appendix A.

The weather conditions were sunny, with temperatures in the 50s and winds of approximately five miles per hour from the south. Surface conditions were relatively dry.

#### 6.1 Underground Storage Tanks (USTs)

No equipment typically associated with USTs was observed on the Property during the on-site inspection.

#### 6.2 Aboveground Storage Tanks (ASTs)/Storage Drums/Containers

A designated hazardous material storage area is located in the addition portion of the structure. The room contains 55-gallon storage drums of alkaline solvents and 100-gallon containers of various plating solutions and rinse tanks. The dip tanks contain alkaline solutions, water rinses, PCE, and cyanide solutions for zinc, gold, silver and copper plating baths. No leaks were observed and no significant cracks in the concrete surface below the storage drums, containers or tanks were noted.



Numerous 55-gallon drums containing process chemicals and petroleum products are located throughout the production area of the structure. These drums should be placed on secondary containment equipment to prevent potential releases to the environment.

#### 6.3 Stained Surfaces/Stressed Vegetation

Minor amounts of petroleum staining were observed throughout the interior of the structure. There was a small amount of staining surrounding the degreaser in the hazardous materials room. No discolored soils or stressed vegetation were observed.

#### 6.4 Stormwater Run-off/Standing Water

Stormwater run-off from the Property appeared to flow into storm sewer catch basins located in the parking lot and adjacent streets. No sheens were noted in the sewers. No unusual odors were emanating from the sewers

#### 6.5 Waste Disposal Practices

The solid waste generated is collected for off-site disposal by Waste Management. According to Mr. McDaniel, the chemical wastes are collected and disposed of by Heritage Environmental on an "as needed basis" and the scrap metal is recycled by Dublin Metals. No additional waste streams were reported or identified being generated from the Property.

#### 6.6 Polychlorinated Biphenyls (PCBs)

Fluorescent light fixtures were observed in the structure. No signs of leakage were observed on the light fixtures. Based on the construction date of the structure, it is possible the ballasts within the fluorescent light fixtures contain PCBs.

According to Mr. McDaniel, air compressors are located above the production area of the structure. Based on the estimated age of the compressors, the fluids contained within the compressors may contain PCBs.

Nine (9) pole-mounted transformers were located near the east Property boundary. The equipment was not observed to be leaking or to be labeled with a black and yellow PCBs warning sticker. A warning sticker is required by federal regulations for equipment containing between 50 and 500 ppm PCBs or greater. ComEd, as the owner of the transformers, is responsible for keeping the equipment in compliance with federal, state and local regulations, and the cleanup of contamination resulting from leaking equipment, as necessary.



No additional equipment that may contain PCBs was identified on the Property.

#### 6.7 Air Quality/Emissions

A solvent odor was noted in the hazardous materials room, emanating from the vapor-degreasing machine.

In addition to the structure's heating sources, Tricon has discharges from plating, vapor degreasing and molding operations. According to Mr. McDaniel, Tricon has air permits (ID#043030ADR) for the previously mentioned operations.

#### 6.8 Readily Visible Suspect Asbestos-Containing Material (ACM)

ACM has been used extensively in the construction of buildings. According to the USEPA, ACM is commonly found in three forms: (1) sprayed or troweled-on ceilings and walls (surfacing materials), including structural fireproofing; (2) in insulation on pipes, ducts, boilers, tanks or mechanical equipment [thermal system insulation (TSI)]; and (3) in "miscellaneous materials," such as, floor tiles, roofing felts and shingles, or wall boards. ACM is of greatest potential concern when it is friable, particularly if it is damaged or deteriorated. Friable, by definition, refers to a material that, when dry, can be crumbled, pulverized or reduced to powder by hand pressure. Friable ACM is more likely than non-friable ACM to release fibers when disturbed or damaged. Airborne asbestos fibers can pose a potential respiratory health risk to building occupants who are exposed.

An all-inclusive survey for the presence of suspect ACM were beyond the scope of services for this Phase I Assessment. As the addition is under construction, the building materials are not suspect of containing asbestos. The following chart summarizes readily visible ACM identified in/on the original buildings of the structure to include, but is not limited to:



HOMOGENEOUS MATERIAL	LOCATION	CONDITION	FRIABLE	NON-FRIABLE
12"x12" floor tile and associated mastic	Various areas throughout the building	Good		Х
Plaster	Walls and ceilings of office areas	Good	·	X
2'x4' drop ceiling panels	Lunchroom	Good	X	
2'x2' glued-on ceiling tile	Various areas throughout the building	Good	Х	
Thermal system Insulation (TSI)	Ducts in original building	Good	Х	
Elbow, valve and tee joint - TSI	Water/steam piping in several areas of structure	Poor	х	
Roofing materials	Roof	Not observed		Х

#### 6.9 Potential Lead-based Paint

Painted surfaces were observed on the structure and appeared to be in overall good condition. Based on the construction date of the original building, the paint may contain lead above regulatory limits.

#### 6.10 Miscellaneous Equipment

Fluorescent light fixtures and thermostats were observed throughout the building. The fluorescent light bulbs and thermostats may contain mercury.

Air conditioning units are located on the rooftop of the Property structure. The air-conditioning units contain chlorofluorocarbon (CFC) refrigerant. CFC refrigerant is a federally regulated substance that is known to contribute to ozone depletion within the atmosphere.

A vapor degreaser is located in the hazardous materials room. This equipment utilizes PCE as a solvent.

#### 6.11 Observations of Surrounding Sites

Visually recognizable environmental concerns were not identified on the adjacent sites, as observed from the Property and public right-of-ways.



#### 7.0 WARRANTY AND LIMITATIONS OF LIABILITY

The Phase I Assessment and this Report are of limited scope, and do not provide sufficient information to eliminate the total risk of the presence of contamination or other liabilities. Significantly higher levels of exploratory efforts than those performed in this Phase I Assessment are required to accumulate sufficient information to determine all environmental liabilities associated with the Property. Subsurface investigations and testing were beyond the scope of this Phase I Assessment.

EPS Environmental warrants that the Phase I Assessment has been conducted in accordance with generally accepted investigatory methods utilized by professional environmental consultants and includes the recommended practices for the "Phase I Environmental Site Assessment Process" contained in the ASTM Standard E 1527-00. EPS Environmental further warrants that the findings and conclusions in this Report are based exclusively on the Phase I Assessment. The investigatory methods that EPS Environmental utilized in the Phase I Assessment have been developed to provide the Client with information regarding apparent indications of existing or potential environmental conditions relating to the Property and are limited to the conditions that were observed at the time of the investigation of the Property. The findings and conclusions contained in this Report are also limited to the information available on the Property at the time that the Phase I Assessment was conducted. There is a distinct possibility that conditions may exist at the Property, which were not apparent during the preparation of the Phase I Assessment. In conducting the Phase I Assessment and preparing the Report, EPS Environmental relied on the information obtained from Property owner/operators or other persons, and government agencies having knowledge of operations and practices of the Property. EPS Environmental has assumed that this information is accurate and complete, except when independent investigation has indicated otherwise.

The Phase I Assessment did not attempt to determine whether the facilities operating on the Property are in compliance with existing environmental regulations. This Report discusses and summarizes areas of potential environmental concern for the Property itself. This Report provides no other warranties, expressed or implied.

#### 7.1 Confidentiality

EPS Environmental will hold the Report and all field observations and related documents in strict confidence and will not disclose these items except to the Client or except as ordered by any state or federal agency or court of law. In the event that EPS Environmental is ordered by a state or federal agency or court of law to disclose the contents of the Report or field observations, the Client shall hold EPS Environmental harmless from liability for any damages that the Client may suffer due to EPS Environmental's disclosure. In addition, the Client shall indemnify EPS Environmental from



any and all damages EPS Environmental may suffer due to any action, which results in an order that EPS Environmental make a disclosure.

#### 7.2 Reliance On Phase I Assessment And Report

The Phase I Assessment has been conducted and this Report has been prepared, exclusively for the Client and it is intended that only the Client will rely on the Phase I Assessment and Report. The Phase I Assessment and Report will be solely for the benefit of the Client and may not be relied upon by other parties.

#### 7.3 Sources of Information Relied Upon For Phase I Assessment and Report


All information that EPS Environmental has relied on in conducting the Phase I Assessment and preparing the Report, not specifically identified as generated by EPS Environmental or any federal, state or local agency, has been supplied by or derived from data provided by the Client and Property representative.



### **FIGURES**


# FIGURE 1 – PROPERTY LOCATION MAP





Streets Plus

2325 Wisconsin Street, Downers Grove, Illinois EPS Environmental Services, Inc., Project #: 3899-1001



TRICON INDUSTRIES, INC. 2325 WISCONSIN AVE. DOWNERS GROVE, IL 60515 LOT SIZE:


12966 m<sup>2</sup>

**BUILDING SIZE:** 

4209 m<sup>2</sup>

MANUFACTURING SIZE:

2095 m<sup>2</sup>





# APPENDIX A PHOTOGRAPHIC DOCUMENTATION

Right: North Property View

**Below: West Property View** 






EPS Environmental Services, Inc.
Project #: 3899-1001

2325 Wisconsin Street

Downers Grove, Illinois


Page 1 of 3





Right: Hazardous Materials Room. 100-gallon dip tanks

Below: Vapor Degreaser (located in the Hazardous Materials Room). It should be noted that this equipment contains PCE.





EPS Environmental Services, Inc.
Project #: 3899-1001

2325 Wisconsin Street

Downers Grove, Illinois

Page 2 of 3

Right: Staining below vapor degreaser



Right: 55 gallon drums stored in receiving area

Below: Interior View of Production Area





EPS Environmental Services, Inc. Project #: 3899-1001


2325 Wisconsin Street

**Downers Grove, Illinois** 

Page 3 of 3

Right: Thermal System Insulation (TSI). It should be noted that this is possible Asbestos Containing

Material (ACM)





# APPENDIX B ENVIRONMENTAL DATABASE INFORMATION



SRP -

USTs -

#### **ENVIRONMENTAL DATABASE DESCRIPTIONS**

NPL -National Priority List for sites targeted for long-term remediation action under Superfund. **CERCLIS** -Comprehensive Environmental Response, Compensation, and Liability Information System for priority cleanup sites or those sites under investigation for possible hazardous waste disposal. RCRIS -Resource Conservation and Recovery Act Information System for facilities that generate, store, transport, treat or disposal of hazardous waste. ERNS -Emergency Response Notification System List of reported hazardous substance releases or spills in quantities greater than the reportable quantity, as maintained at the National Response Center. NIPC -Northeastern Illinois Planning Commission database for active and inactive solid waste disposal sites. LBDS -Land-Based Disposal Sites, a list of active solid waste disposal sites in Illinois. LUST -Leaking Underground Storage Tank Incident Report.

IEPA Site Remediation Program

List of Registered Underground Storage Tanks (USTs).

HANDLER NAME: TRICON INDUSTRIES INC HANDLER ID: ILD005084124

STREET: 2325 WISCONSIN EPA FACILITY ID: ILD005084124

<u>CITY:</u> DOWNERS GROVE <u>CORPORATE LINK:</u> No

STATE: IL COUNTY: DU PAGE

ZIP CODE: 60515 MAPPING INFO: MAP

EPA REGION: 5

#### **CONTACT INFORMATION**

NAME	STREET	CITY	STATE	ZIP CODE	PHONE	TYPE OF INFORMATION
	2325 WISCONSIN	DOWNERS GROVE	IL	60515	(312) 964- 2330	Part A Permit
11	2325 WISCONSIN	DOWNERS GROVE	īL	60515	(312) 964- 2330	Notification

#### HANDLER / FACILITY CLASSIFICATION

HANDLER TYPE	LAND DISPOSAL	INCINERATOR	BOILER AND OR INDUSTRIAL FURNACE	STORAGE	TREATMENT
Small Generator					

Du Page Du Page Du Page Du Page Du Page Du Page	2003084 Closed 2003084 2003084 2003084 2003084 2003084 2003084	Liberty Copper & Wire Co Magnetek Inc 2333 Wisconsin Ave 427 E Stewart St Downers Grove, IL 60515 Milwaukee, WI 5320 Marron, Patrick E. (312) 969-7660	1 2 3 4 5	4000 Hazardous 5000 Hazardous 4000 Hazardous 4000 Hazardous 4000	24 Removed 24 Removed 24 Removed 24 Romovod 35 Exempt from registration
Du Page Du Page	2003084				•

VERSION: 8.01

WASTELAN DATABASE DATE: 05/15/2001

WASTELAN DATABASE TIME: 15:48:36

\*\* PRODUCTION VERSION

U.S. EPA SUPERFUND PROGRAM

05

WASTELAN

Site/Response Action Listing (Transition)

(LIST-08 Transition)

Region:

CITY

SITE NAME

STREET

COUNTY CODE AND NAME (ASSOCIATED SITE NAME)

STATE

ZIP OP ACTION

001

**ACTUAL** START

**ACTUAL** COMPLETE ACTION

03/16/1990

State (Fund)

LEAD

rage Juli Ut 1000

**RELEASE THROUGH FOIA** 

SITE ID	EPA ID NO.	(ASSOCIATED EPA ID)	CONG DIST	UNIT	CODE, NAME	SEQ	DATE	DATE	LEAD
State: 0500433	IL ILD068492206	SUBCON MFG CORP 210 DOWDLE ST ALGONQUIN 111 MCHENRY	IL 6010	2				•	
0506148	ILD068468438	SUBURBAN COMPUTER SERVICES, INC. 150 WEST WILSON PALATINE 031 COOK	IL 6006	00 00	DS DISCVRY PA PA	001 001		04/01/1981 06/28/1985	EPA Fund EPA Fund
0500335	ILD047033188	SUBURBAN SELF STORAGE FACILITY 2333 WISCONSIN AVENUE DOWNERS GROVE 043 DUPAGE	IL 6051	00 00	DS DISCVRY PA PA	001 001		04/25/1989 06/09/1989	State (Fund) State (Fund)
0506163	ILD053191029	SUN CHEMICAL CORPORATION 6600 SOUTH MELVINA AVENUE CHICAGO	L 6063	00 00 00 00 00	PA PA PA PA SI SI	001 001 002 001 001		08/01/1980 12/01/1983 03/02/1993 12/01/1984 09/29/1985	EPA Fund State (Fund) EPA Fund EPA Fund EPA Fund
٠		031 COOK		00	DS DISCVRY	; 001		06/23/1989	State (Fund)

00 PA PA

PAGE: 68 U.S. ENVIRONMENTAL PROTECTION AGENCY REPORT ID: DATE: 04/20/00 CAREGST RCRIS NATIONAL OVERSIGHT DATABASE HANDLERS WITH CORRECTIVE ACTION ACTIVITY -- PART A --050 060 070 075 100 140 150 200 210 225 250 300 340 350 400 450 500 550 600 650 725 750 999 HANDLER NAME ID NUMBER L0 ILDO70686282 KEMMER PRAZISION YEZ YEZ YE YE ILDUZUBLISEL KERR MCGEE CHEMICAL COR YES YES HI YES YES YΕ ILDOOD714881 KEYSTONE GROUP BARTONVI YES YEZ HI YES ILDO47028881 KINCAID GENERATION LLC YES LO ILDOOS465929 KNOEDLER MANUFACTURERS YES YEZ ME ILDUUSI62177 KOMATSU DREESER CO LO ILDOOS164611 KOPPERS INDUSTRIES INC YEZ LO ILDO94760253 KW BATTERY CO YES 4 LO ILDOOL426618 KYANIZE PAINTS INC L0 **AE2** ILDOOGE80606 LACLEDE STEEL CO ALTON YES YEZ HI YES YES YE YE YE YES ILD980S02744 LAIDLAW ENVIRONMENTAL Z YES YEZ ME YES YES YE ILDOJOS97276 LAKE RIVER CORP TERMINA ME ONI ZNOZ GNA R NIVAJ EJZ1757PDGJI ME ILDO47033166 LIBERTY COPPER & WIRE C ILDO75615674 LIFETIME DOORS INC LO ILDOOS265749 LILLY INDUSTRIES INC L0 IN ILDOOSO71808 LINDBERG HEAT TREATING YES AEZ FO ILDUUS442371 LINE TOOL & STAMPING CO YES YEZ LO ILDO74410390 LIQUID DYNAMICS INC HI LO ILDOOGHAALO75 LISSNER CORP ME ILDO25475914 LOGAN BOB TRACTOR CO 23Y DO 231772UDNI RATZ 3NOJ 274E4OBPDJI ME ME IN ILDOOL643659 LONZA INC YES ME ILDOS6623598 LTV STEEL CO CHICAGO WO YES ILDOSARDZEA LUCENT TECHNOLOGIES INC L٥ YE YE YES YES LO YES YEZ YES ILDOLBLOBBLU LUCENT TECHNOLOGY INDIA YES NR ILDOLASOL419 LUNT MFG CO INC L0 ILDOL7478594 MAGIE BROTHERS OIL CO LO ILDD82050576 MANNER PLATING INC YES LO YE YE YES ME YES YES YES ILDOOS476882 MARATHON ASHLAND PETROL YES IN O HZINAAN NITAAM 44P4P54PDGJJ L0 ILDOS773hO35 MASON-DIXON TANK LINES L0 YΕ ILDO25821513 MASONITE CORP L0 I ZTOUGOSQ ZAD NOZHTAM EETELLEDDULI ΗI ILDO67417337 MAYTAG GALESBURG REFRIG ME IN ILDO93746014 MAYTAG HERRIN LAUNDRY P ΗI AM HW TO VID ZJIAN 3XAM 208E7F2000JI L O 23Y ONI YIPQUZ GABL NOODOM BOSEBPBDD11 YES ME YES ME ILDU70487342 MCKESSON CHEMICAL CO

	THOMBU TIMI SEBESBOBPOLI			ME	IN	
	ILDOOSO68762 INDUSTRIAL COATINGS GRO			Ł0		
	DAINITAN STATEM DANNI ELEEDSOBPULE	YEZ	23Y	ΜE		
	ILDOOS213285 INTERNATIONAL HARVESTER			HI	YE	
	ILDOO5236468 INTERNATIONAL PAPER			ME		
	ILDOOS211545 ITT CORP HARPER			LO		
	Z3IRTZUQNI IWI POSP747PDQJI			ΜE		
	ILD047032750 J AND M PLATING INC	YEZ	YES	ME		_
	ILD990783995 J AND M PLATING INC	YES		ΗI	YI	E
	ILDBOLZ82479 JENNISON-WRIGHT CORP TH	YEZ	Z3Y	ΗI	YEZ IN	
	YBAB NOZNHOL & NOZNHOL DZPEZPBJDGJI			L0		
	ILDODITYTTT NOZNHOL PPPPPTLODULIL	YEZ `	Z3Y	L0		
	ILD980502470 JOHNSON CONTROLS BATTER			ME		
	ILDOLO224335 JOHNSON FIRE PROOF DOOR			L0		
	ILDDOO781591 JONES & LAUGHLIN STEEL	YEZ	YES	ΗI	IN	
	ILDODOSOBBEE KALMUZ & AZSOCIATEZ INC	YES		L0		
	ILDU85352474 KEARNEY NATIONAL INC			L0		
l						

ILD005162177	KOMATSU DREESER CO	SUNNYSIDE AVE 871H 21-10011 W	PIDENIIATEEF		555.5	
ILD005164611	KOPPERS INDUSTRIES INC	3VA 3IMARAL 2 DOPE	CHICAGO	IL.	F0F20	
ILD094760253	KW BATTERY CO	TZ GRAWOH 222E	ZKOKIE	ΙL	60076	
ILD00145PP79	KYANIZE PAINTS INC	ILIE N IHTH ST	SPRINGFIELD	IL.	62702	
IF300P590P0P		5 CUT ST	ALTON	ΙL	P5005	
	LAIDLAW ENVIRONMENTAL SVC OF IL INC	LLES N PECATONICA ROAD	PECATONICA	IL	PJ0P3	
ILD010597276		5005 S HARLEM AVE	FOREST VIEW	ΙL	60402	
	LAVIN R AND SONS INC	2028 S SHERIDAN RD	NORTH CHICAGO	IL	60064	
	LIBERTY COPPER & WIRE CO.	3VA NIZNOZIW EEES	DOWNERS GROVE	IL		
ILD075615674	LIFETIME DOORS INC	OFD HMA 54	MATZEKA	<del>- 11</del>	60970	
	* - · - · • · · - · - · · · · - · · ·	· · · · · · · · · · · · · · · · · · ·	MOLINE	ĪĹ	61265	
	LILLY INDUSTRIES INC	5400 23RD AVE	MELROSE PARK	ĪĹ	P07P0	
	LINDBERG HEAT TREATING CO	1975 N RUBY ST	ARLINGTON HEIGHTS	ĪĹ	P0002	
ILD005442371		TA NIUDNODIA W PEC		ΙL	P0P59	
IL0074410390		LSS E 114TH ST	CHICAGO		F0P55	
ILD006931075		1000 N OGDEN AVE	CHICAGO	ΪΓ		
ILD025475914	· · · · · · · · · · · · · · · · · · ·	18LK N OF STATE ST & MIDDLE ST	FRANKLIN GROVE	IL	PO737	•
ILD980613475	LONE STAR INDUSTRIES OGLESBY	PORTLAND AVE	OGFEZBA	15	67348	

REPORT ID: CAREGST

## U-S. ENVIRONMENTAL PROTECTION AGENCY RCRIS NATIONAL OVERSIGHT DATABASE

#### HANDLERS WITH CORRECTIVE ACTION ACTIVITY

PAGE: 67 DATE: 04/20/00

#### -- PART B --

ID NUMBER	HANDLER NAME  LONZA INC  LTV STEEL CO CHICAGO WORKS  LUCENT TECHNOLOGIES INC  LUCENT TECHNOLOGY INDIAN HILL  LUNT MFG CO INC  MAGIE BROTHERS OIL CO  MANNER PLATING INC  MARTHON ASHLAND PETROLEUM LLC  MARTIN VARNISH CO  MASON-DIXON TANK LINES INC THE  MASONITE CORP  MATHESON GAS PRODUCTS INC  MAYTAG GALESBURG REFRIGERATION  MAYTAG HERRIN LAUNDRY PRODUCTS  MAZE NAILS DIV OF WH MAZE CO  MCCOOK LEAD SUPPLY INC  MCKESSON CHEMICAL CO  MCKESSON CHEMICAL CO  MCWHORTER EAST  MCWHORTER TECHNOLOGIES INC  MCWHORTER WEST  MEAD CONTAINERBOARD  MECH-TRONICS CORPORATION  MERCURY FINISHING CO  METAL FINISHING RESEARCH CORP  METAL FREATING AND ENG INC  METHODE ELECTRONICS INC INTRCNCT PROD  METHODE ELECTRONICS INC INTRCNCT PROD  METRO ST LOUIS DRUM SVC INC  MIDLAND-ROSS CORP NAT CASTINGS-CICERO  MIDLAND-ROSS CORP NATIONAL CASTINGS DIV  MIDWEST PRINTED CIRCUIT SVCS  MIDWEST PRINTED	STREET	CITY	12	ZIP CODE
בו אחחזו ווכם כם	I AMA TAK	prr Th	MADIFTON	ΤL	61547
TL DOCUMENTOS 1	TAN CALLI CV CHACYCV HVBAC	111 00 C DUDIES AUC	CHTCAGO	ΤĹ	60617
IL #063303163	THE STEEL TO CUITAGO MOKK?	TIPUU Z DUKLEI AVE	17616	ΤĪ	F0235
TC NO 1 3 1 1 2 1 3 1 3 1 3 1 3 1 3 1 3 1 3 1	FREENT TECHNOLOGIES INC	JODO N NYDEBATILE BY	NADEPUTILE	Ti	h05hb-7033
1	LUCENT TECHNOLOGY INVIAN MILL	EDUU N NAPERVILLE RV	CCHAIMBIRC	TI	เกเลา
TL DOG 0300411	MACTE DEATHERS ATT CA	BIDI U EU LEDTAN AVE	EPANYI TN DARK	TI	เกเสม
TI NOB 79 703 19	MANNED DIVILING INC	TION OF FULLERION AVE	BUCKEUS LUNK	TI	F1111
TLVUUCUSUSTE	MARATURA ARIENT DETERMENT OF	MYDYLOVN YOL	PORTNEON	ΤĹ	62454
TL 70003470002	MANATAN ASALAMA PETKOLEGII ELE	DOD W 118TH OF	CUTCACO	Ti	L0L09
100017617167	MACON_DIVON TAME LIMES INC. THE	100 M 4110 PL	MARCHALI	Τī	L2441
11 103 (138 23 23	MYZVNIIE CVBU	THE DAMES OF	HEST CUTCACO	TI	LDLAS
TC 10C 30C 7373	MATHERON CAR OBODINGTE THE	FISS CAMPS CA & WYNNYLLYN BS	IN TET	TI	LD434
TL DOL DU 1.7227	MAYTAC CALCOURC BEEDICEDATION	MVNWVILL DI NY KTCUNKNY 71 F HWUUNIINM NN	CALECUIRG	TI	L1401
11 708 (41 (33)	MAYTAC UCDOTA LANADOU DOANICTO	HONDOUGH BLVD	PATE 20000	TI	L2948
100013178877	MATE NATIC DID AS DU MAZE CA	AND CHIECU ST	UCBU	TI	L1354
TUCCTBEBUU 11	MCCVVN FEYD CHOOK A THE	3363 N N340 CA	MC CAAY	TI	LN525
TL 70 10 10 300	MCKEZZVN CHEMICYT CV	TION TO THE SHARE AND	CHICAGO	71	LUFUY
150010001100	MCKEZZON CHEMICH CO	3700 2 CMTILOKMIN WAS	CUICAGO	TI	LILDS
11 7001933311	MEHINDELE CYCL	EP31 75MFFF 71	CARDENTERRUTILE	TI	L01.1.0
エトトロのつのこのはコト	MEGUARTER TECUMALACTER THE	CARE HARION RU AND COLLAGE AVE	CARPENIERZATETE	TL	6000
11700210016	MCMHOKIEK LECHNOLOGIEZ INC	374 E JOE ORR ROAD	CHICAGO HEIGHIZ	TI.	מערטט
11,00,5277020	UCMHOKIEK MEZI	COTTAGE AVE	CARPENIERSVILLE .	71	101120
110045702586	MEAD CONTAINERBOARD	JERT Z JOLH WAF	RKINGEATEM	71	10310
10054340772	MECH-IKONICZ CORPORATION	157 N STH AVE	MELROZE PARK	TL	50760
10047406607	WEKCHKA LINIZHING CO	STIS 2 PRATRIE WAF	CHICAGO	T.L.	20026
11.0045700945	METAL FINISHING RESEARCH CORP	4025 S PRINCETON AVE	CHICAGO	16	50507
11,000,004,009	METAL TREATING AND ENG INC	7346 CENTRAL PARK	2K0KIE	Tr	P00 (B
ILD096731468	METALICO GRANITE CITY INC	7500 7P1H Z1	GRANITE CITY	11	PS040
ILD005092135	METHODE ELECTRONICS INC	7444 W WILSON	CHICAGO	IL	PRP2P
ILD046579488	METHODE ELECTRONICS INC INTRCNCT PROD	1700 HICKS RD	ROLLING MEADOWS	IL	60009
1L0077117992	METRO ST LOUIS DRUM SVC INC	3105 MISSOURI AVE	EAST ST LOUIS	IL	P5502
ILD001899772	MICRO SWITCH PLT 4	FAIRGROUND ROAD	FREEPORT	IL	P7035
ILD049015134	MIDLAND-ROSS CORP NAT CASTINGS-CICERO	1400 S LARAMIE AVE	CICERO	IL	F0F20
ILD072317761	MIDLAND-ROSS CORP NATIONAL CASTINGS DIV	IN SITH AVE	MELROSE PARK	IL	20720
ILD059453373	MIDWEST ELECTRIC MFG CORP	ILBR W WALNUT	CHICAGO	IL	PDF75
ILD005149505	MIDWEST PRINTED CIRCUIT SVCS	ኔ74ኔ N CIRCUIT DR	ROUND LAKE BEACH	IL	60073
ILT180013419	MIDWESTERN DRUM SERVICE INC	7500 BIZZELL VAE	VENICE	IL	62090
ILDO68474147	MII INTERNATIONAL INC	2800 SHERMER RD	NORTHBROOK	ΪL	P00P5
ILD054955547	MIKA TIMBER CO	LANDFILL RD	SPARTA	IL	62864
ILD000815357	MOBIL OIL CORP CICERO LUBE PLT	3801 S CICERO AVE	CICERO	ΙL	POP20
ILD064403199	MOBIL OIL JOLIET REFINERY	I 55 AND ARSENAL RD	JOLIET	IL	60434

HANDLER NAME: LIBERTY COPPER & WIRE CO HANDLER ID:

ILD047033188

STREET:

2333 WISCONSIN AVE

EPA FACILITY ID: ILD047033188

CITY:

**DOWNERS GROVE** 

CORPORATE LINK: No COUNTY:

**DU PAGE** 

STATE: ZIP CODE:

 $\Pi$ 60515

MAPPING INFO:

<u>MAP</u>

**EPA REGION:** 

5

#### **CONTACT INFORMATION**

NAME	STREET	<u>CITY</u>	STATE	ZIP CODE	PHONE	TYPE OF INFORMATION
BUILDING SCHANGE	IM/ICCONICINI I	DOWNERS GROVE	IL	60515	(312) 242-4420	Part A Permit
LIVINGSTON LESLIE	IWICONSIN I	DOWNERS GROVE	IL	60515	(312) 242-4420	Notification

#### HANDLER / FACILITY CLASSIFICATION

HANDLER TYPE	LAND DISPOSAL	INCINERATOR	BOILER AND OR INDUSTRIAL FURNACE	STORAGE	TREATMENT
Permit Progress				Y	
Subject to CA					

HANDLER NAME: MAGNETROL INTERNATIONAL INC

HANDLER ID:

ILD089824684

STREET:

5300 BELMONT ST

EPA FACILITY ID: ILD089824684

CITY:

**DOWNERS GROVE** 

**CORPORATE** LINK:

No

STATE:

 $\Pi$ 

COUNTY:

DU PAGE

ZIP CODE:

60515

MAPPING INFO:

<u>MAP</u>

**EPA REGION:** 

#### **CONTACT INFORMATION**

NAME	STREET	CITY	STATE	ZIP CODE	PHONE	TYPE OF INFORMATION
IOSEPH	IRELATINE I	DOWNERS GROVE	IL	60515	(312) 969- 4000	Part A Permit
LIELDER	IRRI MONTE I	DOWNERS GROVE	IL	60515	(312) 969- 4000	Notification

#### HANDLER / FACILITY CLASSIFICATION

HANDLER TYPE	LAND DISPOSAL	INCINERATOR	BOILER AND OR INDUSTRIAL FURNACE	STORAGE	TREATMENT
Large Generator					

**HANDLER** 

STREET:

MXL INDUSTIRES WOODLAND

NAME:

MOLD DIV

2300 WISCONSIN AVE

DOWNERS GROVE

STATE:

CITY:

 ${
m I\!L}$ 

ZIP CODE:

60515

EPA REGION: 5

HANDLER ID:

LLD005130000

EPA FACILITY ID: ILD005130000

CORPORATE

LINK:

COUNTY:

DU PAGE

No

MAPPING INFO: MAP

#### **CONTACT INFORMATION**

NAME	STREET	CITY	STATE	ZIP CODE	PHONE	TYPE OF INFORMATION
ANDERSON RICHARD	IIM/ISCCINISTN I	DOWNERS` GROVE	IL	60515	(312) 969-6100	Part A Permit
MURPHY STEVEN	IIAA ISC CANISTNI - I	DOWNERS GROVE	IL	60515	(630) 960-2288	Notification

No Handler/Facility classification information is available for the facility listed above.

## Bureau of Land

The following LUST incidents matched your search criteria. To display additional information about a selected incident, click on the hyperlinked IEMA #.

IEMA#	LPC#	Site Name	Address	City	ZIP Code	
891092	0430305093	Tucek, Ronald	4250 Lacey Rd.	Downers Grove	60515	
891116	0430305051	D&M Corvette Specialists	1804 Ogden Ave.	Downers Grove	60515	
891117	0430305051	D&M Corvette Specialists	1804 Ogden Ave.	Downers Grove	60515	
	0430305094		Ogden Ave.& Fairview	Downers Grove	60515	
891369	0430305096	Resthaven Nursing Home	3450 Saratoga	Downers Grove	60515	
891490	0430305122	Emro Marketing	5004 Fairview	Downers Grove	60515	
900410	0430305098	MCI Telecoms	501 63rd St.	Downers Grove	60516	
900415	0430305095	Amli Office Partners	3333 Finley Rd.	Downers Grove	60515	
900886	0430305103	Dalise Enterprises	5245 Main St.	Downers Grove	60516	
900986	0430305102	Amoco Oil Co. #9776	2231 Maple St.	Downers Grove	60515	
[3/11]						

Home | State of Illinois | US EPA | Contact IEPA | Disclaimer | Site Map | Search

## Himois Environmental Protection Agency Bristant of Land

The following LUST incidents matched your search criteria. To display additional information about a selected incident, click on the hyperlinked IEMA #.

IEMA#	LPC#	Site Name	Address	City	ZIP Code
903402	0430305121	Uno-ven	1201 East Ogden Ave.	Downers Grove	60515
903727	0430305114	Illinois Bell Telephone	4924 Forest	Downers Grove	60515
910323	0430305135	Thornton Oil Corp. `	1012 Ogden Ave.	Downers Grove	60515
910867	0430305136	Diocese of Joliet	444 East Wilson	Downers Grove	60515
911084	0430305142	Okerson's Service Inc.	356 Maple Ave.	Downers Grove	60515
912105	0430305148	Southland Corp.	63rd & Main St.	Downers Grove	60516
912371	0430305152	Baker Motor Express Inc.	5355 Walnut St.	Downers Grove	60516
913065	0430305158	Suburban Moving & Storage	2400 Wisconsin Ave.	Downers Grove	60515
913221	0430305098	MCI Telecommunications	501 West 63rd St.	Downers Grove	60516
920115		Downers Grove Ice Arena Ltd. Partnership	5501 Walnut Ave.	Downers Grove	60515
[5/11]					

Home | State of Illinois | US EPA | Contact IEPA | Disclaimer | Site Map | Search

## Bureau of Land

The following LUST incidents matched your search criteria. To display additional information about a selected incident, click on the hyperlinked IEMA #.

IEMA#	LPC#	Site Name	Address	City	ZIP Code
921108	0430300008	Rockwell International	8245 South Lemont	Downers Grove	60516
921361	0430305157	Slampak Union 76	4947 Belmont	Downers Grove	60515
921699	0430305172	Hillcrest Elementary, School	1435 Jefferson St.	Downers Grove	60516
922022	0430300021	Delta Sonic Car Wash	1415 Ogden Ave.	Downers Grove	60515
922092	0430305173	Goldsmith, Ruth	1015 Curtiss St.	Downers Grove	60515
922282	0430305175	Sunlife of Canada	1101 West 31st St.	Downers Grove	60515
923187	0430305151	Amoco Oil Co. #8779	6241 Main	Downers Grove	60515
930155	0430305169	Automotive Services	844 Warren Ave.	Downers Grove	60515
<u> </u>	0430305016	Arrow Gear Co.	2301 Curtiss St.	Downers Grove	60515
930513	0430305187	A-Len Automotive Inc.	333 Ogden Ave.	Downers Grove	60515
[6/11]					

Home | State of Illinois | US EPA | Contact IEPA | Disclaimer | Site Map | Search

## Burcan of Land


The following SRP sites matched your search criteria. To display additional information about a selected site, click on the hyperlinked LPC #.

LPC#	Site Name	Street	City	ZIP Code
0430305267	Fairview Maple Plaza	5003 Fairview Plaza	Downers Grove	60515-
0430305023	Moldtronics, Inc.	703 Rogers Street	Downers Grove	60515-
0430305029	Morey Corporation	2659 Wisconsin Street	Downers Grove	60515-
0430300008	Rockwell International	8245 South Lemont Road	Downers Grove	60516-


Home | State of Illinois | US EPA | Contact IEPA | Disclaimer | Site Map | Search




# APPENDIX C HISTORICAL INFORMATION




	AERIAL PHOTOGRAPH	ी North
PROPERTY ADDRESS	EPS ENVIRONMENTAL SERVICES, INC.	YEAR
2325 Wisconsin Street Downers Grove, Illinois	7237 West Devon Avenue Chicago, Illinois 60631	1951



	AERIAL PHOTOGRAPH	ी North
PROPERTY ADDRESS	EPS ENVIRONMENTAL SERVICES, INC.	YEAR
2325 Wisconsin Street Downers Grove, Illinois	7237 West Devon Avenue Chicago, Illinois 60631	1970



	AERIAL PHOTOGRAPH	ប់ North
PROPERTY ADDRESS	EPS ENVIRONMENTAL SERVICES, INC.	YEAR
2325 Wisconsin Street Downers Grove, Illinois	7237 West Devon Avenue Chicago, Illinois 60631	1980



	AERIAL PHOTOGRAPH	ी North
PROPERTY ADDRESS	EPS ENVIRONMENTAL SERVICES, INC.	YEAR
2325 Wisconsin Street Downers Grove, Illinois	7237 West Devon Avenue Chicago, Illinois 60631	1990
	Chicago, minois 000.71	



# APPENDIX D ENVIRONMENTAL QUESTIONNAIRE

Гал	• T (^	ハンスコンススト	~ a	ŧ
	:			
		Post-	it F	å

To

Fax #

st-it* Fax Note	7671	Date 10-31	# of pages ►
BRIAN Th	emA5	From	
	<del></del>	To.	

ULL UL UL

Co./Dept. Phone #

Co. Phone #

1.01

environmenta

#### **ENVIRONMENTAL OUESTIONNAIRE (002)**

Name:	·	RICON TUdusTRIES
		: 2325 WISCONSIN ST. DOWNERS GROVE, ITLL. 6051
A. CUF	RRENT/F	ORMER USES OF PROPERTY
; <b></b>		
:	1.	Do you own the property? YES
· 		a. Date property was purchased. 1959
		b. If leased, date of first lease on property. N/A
	2.	Description of current use of the property, please be specific, including number of retail or commercial units.  MANUFACTURING/IN189 / IN189 TION MOLDING
÷ ·		a. Number of occupied units?
•		b. Number of unoccupied units? V/A
	3.	Date original construction on property was completed. 1962
	4.	Date of subsequent additions/renovations. 1983
	5.	Description of previous use(s) of the property, please include company names if known.  EMPTY LOT
B. DIS	CHARG	ZS .
•·•	1.	Are there any sources of waste water, stormwater, or other liquid discharges to surface water, septic system, holding ponds or other on-site retention areas?
•	2.	Are there any sources of discharge to the public sewer system?
		YesNoUnknown
•	3. ·	Do these discharges require a permit?
		YesNoUnknown
		If yes, please provide details.
		WASTEWATER TRANTMENT FOR PLATING DEPARTMENT
		(see PROCESS PLOW diAgram)
		DOWNERS GROVE JANITARY DISTRICT PERMIT + 2
	<del></del>	

7237 West Devan Avenue • Chicago, Illnois 60631

[773] 792-9090

Fax [773] 792-3091



#### C. HEATING/COOLING SYSTEM

Describe past and current heating and cooling system for the improvements on the property.

NATURAL 995 LEATING (1) ONE DOILER FOR DRIGINAL

STRUCTURE & ROOF TOP HIAC. UNITS 1.

### D. FUEL/CHEMICAL STORAGE TANKS AND STORAGE DRUMS/CONTAINERS

1. Are there any above or below ground storage tanks on the subject prop	erty?
--	-------

1 UN TOUROUS JUSTICE SEE

· ·	Yes	<b>∠</b> No		_Unknown	
	Тя	nk #1	Tauk #2	Tank #3	Tank #4
Above or underground?				-	-
Location?	-	<del></del>			
Contents?					
Capacity?	_	<b></b>			
Installation date?				***************************************	
Registered?			-		
Special permitting?					
Inspections or tested?		_	***************************************	* ************************************	
Periodic monitoring?		- <b>-</b> -			
Spills, leaks or releases?					grander.
2.	Have any st	orage tanks be	en removed fi	rom the property is	the past?
-	Yes	KNO		_Unknown	

If yes, please provide details.



	3.	re any other chemicals stored on the property in storage drums or other containers?
	•	Yes No _Unknown
		Tyes, please provide contents and location.  See Chemical Storage Listing
, HA	ZARDOU	SPECIAL WASTE
• :	I.	ist all hazardous/special wastes generated or stored on the property.  See BNUIRON MENTAL COMPLIANCE - WASTE MANAGEMENT  WORK IN STRUCTION:
	2.	Describe any processes on site that require storage, treatment or disposal of chemicals, special or hazardous astes or other regulated materials.  PLATING & VAPOL DEGREESING
· :	3.	On these processes require permitting or regulation from any federal or state agencies.  YesNoUnknown
	T.E.P.A	fyes, please provide details. AIR PERMITS / NESHAP
	4.	Describe how the special or hazardous waste generated or stored on the property are disposed?
F, PÓI	YCHLOR	NATED BIPHENYLS (PCBs)
	i.	Tave polychlorinated biphenyls (PCBs) been used in electrical transformers, capacitors, light beliasts, sydraulic systems or other equipment at the property?
		_Yes
		f yes, please describe the use and location of possible PCB containing fixtures and equipment
	2.	lave there been any studies, sampling or testing for PCB's on the property?
		_Yes

3.30




~	TACK BURNEY TOTAL	AM/		ANTO PATERNANT AV
			A 1 17 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	A NII Y 1 YI CIJI YE A I
u.	COMMON WA	COLD OF MEN	ALLIUN A	AND DISPOSAL

	G. CON	MMON W	ASTE GENER	LATION AND DIS	POSAL.	
						toods and a second section of
		1.		estion g		her than waste water) generated at the property.
		2.	How do you di	spose of your solid	and/or liquid wastes! L みとってんせん ハ	ist conunercial waste hauler, if applicable.
		3	Have there bee	en any violations, fi	nes or actions taken by r	egulatory agencies due to this generation?
	: . * · :		Yes	<b>∠</b> No	Uaknown	
	• •		If yes, please p	rovide details.	•	
	H. AIR	EMISSIC	anc		•	
		1.	List all sources burned.	s of air discharges f LATING, U	iom the property. Includ APOR degRens	defuel burning equipment and describe type of fuel the Makel Mag Eperation s
	٠,	2. ,	Are air emissi	ons required to be p	emutted or monitored?	
			Nes.	No	Unknown	
4		2	If yes, please d  LifeTim  TD# 0	lescribe.  78 SPERAT  43030 ADR	ing permit A	Ca) NAPOR dagransee  (3) NAPOR dagransee  (3) INJECTION MELDING MACHINES  emissions on the property?
		3.	L'es	No	Unknown	emissions on the property?
‡	. • `		_		<del></del>	_
			CARbo	w media	Air cleaner:	<b>.</b>
	I. ASB	ESTOS		•		
		1.	Is there asbest	os currently in any	of the construction mater	rials contained in the building(s)?
			Yes	No	Unknown	
			lf yes, please i	ndicate the location	LS.	
		2.	Has an asbesto	ns survey or air sam	pling been performed?	
			_Y&	No	Unknown	
					4	
	٠					•

1.000



				,						
			3.	Has asbe	stos been removed fi	om the building(s	s) in the past?			
				Yes	No	Unkn	Own			
			4.	Do you l	nave an Operation an	d Maintenance of	: Asbestos Manager	nent Program in	place?	
,				Yes	No	Unkn	0wn			
		J. LEA	D BASEI	TAINT						
	3 · · · · · · · · · · · · · · · · · · ·	; ;	1.	Are ther	e any structures on th	ie property which	contain or have con	ntained lead base	d paint?	
				Yes	No	Unkn	own			
			٠.	lfyes, pi	ease indicate the loca	atious.				
			2.	Has a le	ad based paint survey	been performed?	,			
		; ·		_Yes	No	Unko	own			
		:	3.	Do you	have an Operation ar	id Maintenance o	r Lead Based Paint	Management Pro	gram in place?	
•				_Yes	No	Unkn	own			
		:K. M	SCELLAI	<b>EOUS</b>						
			I.		re ever been any f nated site or which is			onto the prope	aty which original	led from a
				Yes	No	Unkn	IOWII			
		: · ·	2.		e now or have there see treatment or wast		any Pits, Ponds. or	Lagoons located	on the property in	connection
		2°		Yes	No	Unka	10MI			
			<b>3</b> .	Is there	currently any stained	soil on the prope	arty?			
		i.	•	Yes	No	Unkr	lown .			
•			4.	a	Have there ever bee	en any previous E	invironmental Site	Assessments or A	audit Repons?	
1		: :			Ycs	No	Unknown			
				b.	Do you have access	to them? If so, p	olease provide copie 5	s.	•	



	5.	<b>8</b> .	Have any resear		drogeologic conditions	or Geotechnical Star	dies been cond	ucted for the
	•		Yes	No	Unknown			
		<b>b.</b> .	Do you have acc	cess to them? If a	so, please provide copi	<b>es</b> .		
			Yes	_No				
· · # . · · · •	. <b>6</b> ,	Does the	e property require	Material Safety	Data Sheets (MSDS),	and/or a Community l	Right-to-Know	Plan?
		Vies	No	U	Inknown			•
	7.	Mas said been est	SDSOA ety plans, prepare ablished for the pr	duess and preve roperty, and have	ntion plans, spill preventes they ever had to be ex	ention, countermeasusercised?	ire and control	plans, ever
: :		Yes	No	U	Inknown			
		if yes, p	lease describe. ANS ARE	IN PLAC	es They h	ave Never	been e	xercise.
L. AI	DIACENT	PROPER	MES					
	1.	comme	icial printing faci	ility, dry cleaner	ting properties been uses, photo developing is recycling facility?			
:		Yes	No	·u	Inknown			
		If yes, p	lease describe.					
м G	OVERNM	ENT EN	ORCEMENT A	CTIONS				,
	1.	<b>8.</b> .	courts relating t	to past or curren	re of notices or other of at violations of environme bility, or to environme	nmental laws with i	respect to the	Property, to
			Yes	No	Unknown			
:		<b>5</b> .	Do you have acc	cess to them? If s	io, please provide copie	<b>35.</b>		
• .			Yes	No				
	2.	a.		of any other connection with th	documents that may as Property?	be significant to R	lecognized Eu	ls/namoniv
1			_Yes	No	Unknown 6		,	

1 は人・エリングリン ブリュミドロ 金字



,就是一个人,我们就是一个人,我们就是一个人,我们就是一个人,我们就是一个人,我们就是一个人,我们就是一个人,我们也会会一个人,我们也会会会一个人,我们也会会 第二十二章 "我们就是一个人,我们就是一个人,我们就是一个人,我们就是一个人,我们就是一个人,我们就是一个人,我们就是一个人,我们就是一个人,我们就是一个人,我


		b.	Do you have	access to the infor	mation? If so, please provide copies.	
			Yes	No		
	3.	a.			pending, threatened, or past litigation relevant to Hazardous Substation the Property?	ಉಣ
			Yes	No	Unknown	
		b.	Do you have	access to the infor	mation? If so, please provide copies.	
			Yes	No		
	4.	<b>a.</b>	Do you have Hazardous	t knowledge of ar	ny pending threatened, or past administrative proceedings relevan	nt to
			Substances of	r Petroleum Produ	cts in, on or from the Property?	
			Yes	No	Unknown	
:		b.	Do you have	access to the infor	mation? If so, please provide copies.	
	,		Yes	No		
· ·	5.	а.			notices from any governmental entity regarding any possible viole liability relating to Hazardous Substances or Petroleum Products'	
			Yes	No	Unknown	
		b.	Do you have	access to the infor	mation? If so, please provide coples.	
<u>:</u>			Yes	No		
As the the info	present ermation	owner of disclosed	the property or a labove is true a	as a duly authorize ad accurate and no	d representative of such owner, I state that to the best of my knowle material information has been withheld.	edge,
LA (Name	RRY	M <	DANIEL		10/29/01 (Date)	
(Signa	nure) /	7 2	ne Dom		(Date) (Date)  PLANT MANAGER (Title)	



Instruction; W4.9.10	Issuer: Larry McDaniel
Issued Date: 4 / 26 / 01	Rev Date: 4/26/01

### 4.10 CHEMICALS ON HAND AND QUANTITY

CHEMICAL Acetone	<u>QUAN</u> 3.8	ITITY liters
Actane 73	100	
		lbs.
Actane 342	100	lbs.
Alkleen 501	5	Gal.
Ammonium Hydrate	40	lbs.
Benzotriazole	55	Gal.
Boric Acid	5	lbs.
Copper Cyanide	5	Gal.
Deox	55	Gal.
Electrolytic Nickel	35	Gal.
Enbond Q-527	100	lbs.
EDM 244 (Dielectric Fluid)	55	Gal.
EDTA	5	lbs.
Enplate NI-416 M	150	Gal.
Enplate NI-416 R	1	Qt.
Enplate NI-416 S	1	Qt.
Fluoboric Acid	100	ml
Hydrochloric Acid	10	lbs.
isopropyl Alcohol	55	Gal.
Nickel Sulfamate	30	Gal.
Nitric Acid	10	liters
Oakite #3	100	ibs,
Oakite Metal Sheen	5	Gal.
Orosene 80 Brightener	2	Gal.
Orosene 80 Buffer Salts	20	lbs.
Orosene 80 Gold Plating Solution	30	Gal.
Orosene 80 Gold Salts	5	OZ
Orotemp 24 Buffer Salts	10	lbs,
Orotemp 24 Gold Salts	5	OZ
Perchloroethylene	160	Gal.
Phosphoric Acid	1	Gal.
Potassium Copper Cyanide	_5	Gal.
Potassium Cyanide	75	lbs.
Potassium Hydroxide	5	lbs.
Potassium Silver Cyanide	100	OZ
Silver Brightener E-2	2	Gal.
Silver Cyanide Plating Solution	30	Gal.
Silver Brightener B-2	1	liter
Sodium Cyanide (Hydrocyanic Acid)	2.5	kg
Sodium Dichromate	5	lbs.
Sodium Hydroxide	4	liters
Sodium Hypochlorite	110	Gal.
Sulfuric Acid	15	liters
-		Gal.
Tower Hydraulic Oil	220	Gal.





# APPENDIX E EPS ENVIRONMENTAL QUALIFICATIONS



#### PETER N. PARTIPILO, C.H.M.M.

- \* Phase I Environmental Property Assessment
- Subsurface Soil and Ground Water Investigation
- Underground Storage Tank Assessment, Removal and Closure \* Asbestos Hazard Assessment and
- Supervision of Phase III Contaminated Site Remediation
- Compliance Auditing
- \* Lead Inspection and Abatement

and Remediation Management

#### PROFESSIONAL REGISTRATIONS/CERTIFICATIONS

- \* Certified Hazardous Materials Manager
- \* Licensed Asbestos Inspector, State of Illinois Department of Health
- \* Licensed Lead Inspector, State of Illinois Department of Health

#### **EDUCATION**

University of Wisconsin, College of Engineering - "Soil and Groundwater Remediation Methods and Technology Course" and "Subsurface Monitoring Strategies Course"

Environmental Group Services - "Asbestos Inspectors Course" and "Asbestos Contractor Course"

Government Institutes - "Groundwater Hydrogeology Course"

Moraine Valley Community College; Environmental Institute - "Asbestos Building Inspector Course", "Asbestos Building Inspector Refresher Course", "Environmental Audits of Real Estate Course", "Environmental Compliance Auditing Course", "Wetland Course", "Sick Building Syndrome", "Pretreatment/Industrial Waste Water Course" and "Lead Inspector Course"

National Water Well Association - "Legal Implications of Environmental Site Assessments Seminar"

Illinois Institute of Technology - "Certified Hazardous Materials Manager Review Course"

#### PROFESSIONAL EXPERIENCE

#### EPS Environmental Services, Inc.

Senior Environmental Specialist \* February 1992 - Present

Performs Phase I Environmental Property Assessments and Phase II subsurface soil and groundwater investigations, testing and sampling and wetlands studies. Manages and oversees underground storage tank assessments, removals and remediations. Handles asbestos and lead surveying, sampling, assessment and abatement.

#### U.S Environmental Testing and Consultants, Inc.

Project Coordinator \* 1989 - January 1992


Managed and oversaw testing, removal, and remediation of leaking underground storage tanks. Evaluated hazardous materials handling practices. Performed environmental property assessments.

#### Team Company

Project Coordinator \* 1975 - 1989

Designed strategies and supervised removal of above and below ground storage tanks. Inspected for asbestos on commercial industrial properties.

#### SAMUEL T. BODINE



- \*Contaminant Characterization and Delineation
- \*Remedial Design Pilot Studies
- \*Leaking Underground Storage Tank Closure
- \*Phase I Environmental Property Assessment
- \*Remedial Options Evaluation
- \*Remediation System Design and Installation
- \*Subsurface Soil and Groundwater Investigation
- \*Licensed Asbestos Inspection

#### PROFESSIONAL REGISTRATIONS/SOCIETIES

- \* Member of the Environmental Bankers Association 1999-Present
- \* Member of the Illinois Association of Environmental Professionals 1994-1999

#### EDUCATION

B.A., Environmental Studies and Biology, Lake Forest College, 1994
40-Hour OSHA 29CFR1910.120 HAZWOPER
8-Hour OSHA 29CFR1910.120(E) Site Supervisor
AHERA Asbestos Building Inspector & IDPH Licensed
Asbestos Contractor Supervisor (OSHA Competent Person) & IDPH Licensed
Accredited Site Assessor by the State of Wisconsin

#### PROFESSIONAL EXPERIENCE

#### EPS Environmental Services, Inc.

Senior Project Manager \* February 2001 - Present

Performs or supervises Phase I Environmental Property Assessments and subsurface soil and groundwater investigation. Manages and oversees leaking underground storage tank (LUST) sites, UST removals and IEPA Site Remediation projects.

#### Bank One Corporation

Environmental Risk Officer \* May 1999 - February 2001

Developed strategies and solutions to mitigate the environmental risks for the bank. Quantified the environmental risks to provide remediation costs for lenders. Maintained list of approved environmental consultants and contract with firms to conduct assessments & investigations on behalf of the bank. Responsible for integrating the bank's environmental policies & procedures and managing environmental credit risks for all lending activities. Reviewed and evaluated environmental assessment reports, provided technical expertise and advice to relationship managers to support the credit review process.

#### Carlson Environmental, Inc.

Senior Project Manager \* July 1994 - May 1999

Managed and conducted large-scale field investigations, remediations and prepared associated reports for heavy industrial facilities. Worked as Health and Safety Coordinator and Equipment Manager preparing proposals and budgets, direct contact with clients and regulatory agencies, designed field investigation work plans and complete documentation/reports for clients or submission to regulatory agencies. Conducted RCRA Facility Investigations, closure of LUSTs, negotiating "closure" of environmentally impacted sites under the IEPA Site Remediations Program and



#### SAMUEL T. BODINE (cont.)

conducting large-scale soil and ground water investigations. Conducted Phase I Environmental Assessments throughout the United States and Canada. Conducted Phase II Limited Subsurface Soil and Ground Water Investigations. Provided oversight for UST removals and LUST remediations. Prepared applications for wastewater / storm water discharges and air pollution control applications.



#### Brian J. Thomas

#### **AREAS OF EXPERTISE**

- \* Phase I Environmental Property Assessment
- \* Property Transaction Screen Assessment
- \* Asbestos Inspection

#### PROFESSIONAL AFFILIATIONS/CERTIFICATIONS

Licensed Asbestos Professional (Inspector) State of Illinois Department of Health and Indiana Department of Environmental Management.

#### **EDUCATION**

Bachelor of Science in Environmental Science, Bowling Green State University, Bowling Green, Ohio

#### PROFESSIONAL EXPERIENCE

#### EPS Environmental Services, Inc

Project Manager\* May 2001 - Present

Head of the Phase I Environmental Property Assessment Department. Responsible for price quotes, client contact, scheduling, facility inspections and report generation. Performs asbestos sampling.

#### Clean Air Engineering

Project Leader\*January 2001 to May 2001

Performed compliance testing to the satisfaction of regulatory agencies. These tests include: Sampling for dioxin/furans, hexavalent chromium, volatile/semivolatile organics and heavy metals. Particulate, SO2, NOx, THC and other criteria pollutant emissions testing. VOC capture and destruction efficiency testing. Continuous emissions monitor certification testing. Hazardous air pollutant (HAPs) emissions testing. Fourier Transform Infra-Red (FTIR) Testing and Monitoring

#### Nicor Natural Gas, Inc.

Mercury Analyst\*August 2000 to January 2001

Visually inspect Nicor gas regulators and homes for possible mercury contamination. Conduct air sampling of homes with possible mercury contamination using Jerome 411 & 431 mercury vapor analyzers. Document results of the testing in great detail and handle customer relations. Personally train incoming contractors.



# APPENDIX F PROPOSAL BETWEEN CLIENT AND EPS ENVIRONMENTAL



### environmental services, inc.

#### **PROPOSAL**

#### PHASE I ENVIRONMENTAL PROPERTY ASSESSMENT

Prepared For:

American National Bank & Trust Company of Chicago 120 South LaSalle Street Chicago, Illinois 60603

Property Address:

2325 Wisconsin Avenue Downers Grove, Illinois

Project Number:

3899-1001

October 18, 2001



#### **PURPOSE**

The purpose of this Proposal for a Phase I Environmental Property Assessment is to provide American National Bank & Trust Company of Chicago (Client), with EPS Environmental Services, Inc.'s (EPS Environmental) proposal and estimated cost of conducting a Phase I Environmental Property Assessment of 2325 Wisconsin Avenue, Downers Grove, Illinois (Property). The purpose of the proposed Phase I Environmental Property Assessment (Phase I Assessment) will be to identify readily apparent, potential sources of environmental liabilities associated with the Property, based exclusively upon the scope of services set forth and agreed upon.

#### SCOPE OF SERVICES

The scope of services to be performed by EPS Environmental, in order to identify areas of environmental concern, will be consistent with the recommended practices set forth in the "Phase I Environmental Site Assessment Process" contained in the American Society for Testing and Materials (ASTM), Standard E 1527-00, and will include the following:

#### A. Records Review

- 1. Physical Setting Sources
  - a. Review United States Geological Survey 7.5 Minute Topographic Map for topography of the Property and surrounding area.
  - b. Review State Geological Survey for published information regarding the surficial geology of the Property.
- 2. Federal and State Record Sources Review the following published environmental databases for the Property and sites within the Approximate Minimum Search Distances as designated by ASTM:
  - a. Federal National Priority List for hazardous substance release sites targeted for long-term remediation action under Superfund.



- b. Federal Comprehensive Environmental Response, Compensation, and Liability Information System for priority cleanup sites or those sites under investigation as potential hazardous substance release sites.
- c. Federal Resource Conservation and Recovery Act Information System for facilities that generate, transport, store, treat, or dispose of hazardous waste.
- d. Federal Emergency Response Notification System List of reported hazardous substance releases or spills in quantities greater than the reportable quantity, as maintained at the National Response Center.
- e. State landfill and/or solid waste disposal sites.
- f. State list of hazardous waste sites, which is the State equivalent to the National Priority List and the Comprehensive Environmental Response, Compensation, and Liability Information System, for sites identified for investigation or remediation.
- g. State leaking underground storage tank list.
- h. State registered underground storage tank list.
- 3. Historical Sources Review or contact one or more of the following reasonably obtainable sources of information to determine the historical uses of the Property from the present back to the Property's first developed use or to 1940, whichever is earliest:
  - a. Sanborn Fire Insurance Maps of the Property for prior uses and locations of fuel and/or chemical storage tanks and storage of other potentially toxic substances.
  - b. Historical aerial photographs for indications of previous uses.
  - c. Local Building Department regarding structures, installations, removals, licenses and permits that may reflect an environmental condition of the Property.
  - d. Local Fire Department regarding the use or storage of hazardous substances or petroleum products on the Property.



- e. Local Health or Environmental Department regarding any known environmental occurrences associated with the Property.
- f. Zoning Department regarding zoning restrictions on the Property.

#### B. Site Reconnaissance

- 1. Visually and physically observe the Property in an attempt to identify readily apparent, potential sources of environmental liabilities including:
  - a. General Site Setting
    - 1. Current and past uses of the Property
    - 2. General description of structures and roads
    - 3. Potable water supply
    - 4. Sewage disposal system
  - b. Interior and Exterior Observations
    - 1. Dead or distressed vegetation
    - 2. Disturbed or stained soils and surfaces
    - 3. Drains or sumps
    - 4. Hazardous substances and petroleum products
    - 5. Heating/cooling system
    - 6. Pits, ponds, lagoons or standing water
    - 7. Point sources of effluent discharges and air emissions
    - 8. Polychlorinated biphenyl (PCB)-containing electrical equipment
    - 9. Potential lead based paints
    - 10. Surface impoundments
    - 11. Suspect asbestos containing materials
    - 12. Waste disposal and housekeeping practices
    - 13. Wastewater discharge
    - 14. Water wells and septic tank systems
    - 15. Underground or aboveground storage tanks, storage drums or containers
    - 16. Unusual or noxious odors



- 2. Visually and physically observe the surrounding sites, from the Property and public right-of-ways, in an attempt to identify readily apparent, potential sources of environmental liabilities posed by adjacent land use.
- 3. Provide photographic documentation of significant environmental features.

#### C. Interviews

- 1. Interview Property or facility owner, operator or key personnel for information indicating environmental conditions in connection with the Property.
- 2. Submit an environmental questionnaire to present Property or facility owner or operator for information regarding environmental liens or additional specialized knowledge concerning the Property.
- D. EPS Environmental will prepare a final Phase I Assessment Report (Report) for the Client containing the observations and Conclusions of the site findings. The Report will be based exclusively upon the scope of services outlined above. Findings and Conclusions in the Report will be rendered based on accepted industry standards, but are not to be construed as a guarantee or warranty as the potential liability associated with environmental conditions or impacts on the Property.

#### WARRANTY AND LIMITATION OF LIABILITY

The Phase I Assessment will be of limited scope, and will not provide sufficient information to eliminate the total risk of the presence of contamination or other liabilities. Significantly higher levels of exploratory efforts than those performed in the proposed Phase I Assessment are required to accumulate sufficient information to determine all environmental liabilities associated with the Property.

EPS Environmental warrants that the Phase I Assessment will be conducted in accordance with generally accepted investigatory methods utilized by professional environmental consultants and will include the recommended practices for the "Phase I Environmental Site Assessment Process" contained in the ASTM Standard Practice E 1527-00. EPS Environmental further warrants that the Findings and Conclusions in the Report will be based exclusively on the Phase I Assessment. The investigatory methods that EPS Environmental will utilize in the Phase I Assessment have been developed to provide the Client with information regarding apparent indications of existing or potential environmental conditions relating to the Property and are limited to the conditions that



will be observed at the time of the investigation of the Property. The Findings and Conclusions contained in the Report will also be limited to the information available on the Property at the time that the Phase I Assessment is conducted. There is a distinct possibility that conditions may exist at the Property which will not be apparent during the preparation of the Phase I Assessment. In conducting the Phase I Assessment and preparing the Report, EPS Environmental will rely on the information obtained from Property owner/operators or other persons, and government agencies having knowledge of operations and practices of the Property. EPS Environmental will assume that this information is accurate and complete, except when independent investigation indicates otherwise.

The Phase I Assessment will not attempt to determine whether the facility operating on the Property is in compliance with existing regulations. The Report will discuss and summarize areas of environmental concern for the Property itself. The Report will provide no other warranties, expressed or implied.

#### CONFIDENTIALITY

EPS Environmental will hold the Report and all field observations and related documents in strict confidence and will not disclose these items except to the Client or except as ordered by any state or federal agency or court of law. In the event that EPS Environmental is ordered by a state or federal agency or court of law to disclose the contents of the Report or field observations, the Client shall hold EPS Environmental harmless from liability for any damages that the Client may suffer due to EPS Environmental's disclosure. In addition, the Client shall indemnify EPS Environmental from any and all damages EPS Environmental may suffer due to any action which results in an order that EPS Environmental make a disclosure.

#### RELIANCE ON PHASE I ASSESSMENT AND REPORT

The Phase I Assessment and Report will be conducted exclusively for the Client and Harris Bank, and it is intended that only the Client and Harris Bank will rely on the Report. The Phase I Assessment and Report will be solely for the benefit of the Client and Harris Bank, and may not be relied upon by third parties.



### SOURCES OF INFORMATION RELIED UPON FOR PHASE I ASSESSMENT AND REPORT

All information that EPS Environmental will rely on in conducting the Phase I Assessment and preparing the Report, not specifically identified as generated by EPS Environmental or any federal, state, or local agency will be provided by or derived from data provided by the Client and/or the Property owner.

#### COMPENSATION

Compensation for the Phase I Assessment work as summarized in this Proposal is pursuant to the attached Compensation Schedule.

#### SCHEDULE

Con

EPS Environmental will commence work upon receipt of a signed copy of this Proposal. The scope of services will be completed within fifteen (15) to eighteen (18) working days from the commencement date, provided access is granted in a timely manner.

#### PERMISSION TO ENTER

I, the undersigned, do horeby represent that I am the owner of the Property or the agent of the owner with power to grant right of entry thereon. I hereby grant permission to any employees or agents of EPS Environmental to enter upon the Property to provide the services previously stated.

Signature:	80 ) Date: 18 OCT 01
Print Full Name: CHEISTER	J.O
	wan

proposity contact: Jay Winkler UP Operations
Tricon Industries
6 630/964 2330